


田中学園様内装工事

(会社名)



体育館手摺施工前

2021:11:09 13:44:41



体育館手摺施工前

2021:11:09 13:27:21



鏡扉施工前

2021:11:09 13:17:16



暖房機施工前

2021:11:09 13:17:19



暖房機施工前

2021:11:09 13:17:18




暖房機ダクト下地施工



暖房機ダクト下地施工



暖房機ダクト下地施工



暖房機ダクト仕上げ



暖房機ダクト仕上げ



暖房機囲い下地状況

2022:02:16 17:10:02



暖房機囲い下地状況

2022:02:16 17:10:14




暖房機囲い下地状況



暖房機囲い下地状況

2022:02:17 11:48:22




暖房機囲い仕上げ



暖房機囲い仕上げ




暖房機囲い仕上げ



手摺下地施工状況




手摺下地・仕上げ状況



手摺下地状況




手摺下地状況




鏡扉仕上げ状況



鏡扉仕上げ状況



鏡扉仕上げ状況



鏡扉仕上げ状況



手摺仕上げ全景



I鏡扉仕上げ全景



演説台

2022:02:25 10:22:38




演説台

2022:02:25 10:22:42



演説台

2022:02:25 10:22:57




演説台

2022:02:25 10:23:41



暖房・扉仕上げ

2022:02:25 10:29:50



暖房仕上げ

2022:02:25 10:29:57